

- 1. BRAVO NET STATION RELOCATED TO OPPOSITE SIDE OF HANGAR. TWO DIPOLES INSTALLED AND WORKING WELL. INSTALLED INTERCOM BETWEEN BRAVO AND BW/OPS POSITION FOR CLOSE COORDINATION DURING MISSIONS. GREATER FREQ SEPARATION RTTY/BRAVO HAS VIRTUALLY ELIMINATED INTERFERENCE TO BRAVO WITHOUT AFFECTING QUALITY RTTY. WHEN ADDITIONAL SAC KWM-2 ARRIVES, EVERYTHING SHOULD BE IN GOOD ORDER HERE.
- 2. OBTAINED SERVICES CHERRY PICKER 3 MAY. ANTENNAS TIGHTENED AND BONDED TO GROUND.
- OSG WIRE/CRYPTO TECH, VISITED 9 25X1A

 MAY AND CURED MAJORITY TTY PROBLEMS. PASR REPERF BEYOND SCOPE

 25X1A FIELD REPAIR; WILL RETURN TO ALL OTHER TTY EQUIPMENT IN

 GOOD ORDER.
 - 4. ONCE ADDITIONAL BRAVO NET EQUIPMENT ARRIVES AND OPERATING,

25X1A PLAN RELEASE

FOR RETURN

Sel CAL WORKING AND COMMO

5. ROUTINE WELL ESTABLISHED, U":-) 294(8,&-,\$:9..9

KUNNING SMOOTHLY

47,,8,& .995#)6. OPTIMISTIC THAT HF VOICE/BW FOR OPERATIONAL

MISSIONS ON BRAVO NET WILL PROVIDE DESIRED COVERAGE. PERSONNEL

GETTING SUFFICIENT TIME OFF FOR LEISURE WITH MINIMUM OVERTIME.

Approved For Release 2001/07/28 - ACIA-REP 75 B0044 6 R000109 200037-0

| FILE INFO | | | | |
|-----------|---|--------------|--------------|----|
| | | REPRODUCTION | N PROHIBITED | |
| ACTION | 1 | 6 | 11 | 16 |
| | 2 | 7 | 12 | 17 |
| | 3 | 8 | 13 | 18 |
| | 4 | 9 | 14 | 19 |
| | 5 | 1ø | 15 | 20 |

E-2 IMPDET

SECRET

BT